

# General Environmental Incident Summary

**Incident:** 4037      **Date/Time Notice:** 3/9/2016      1346      **DEM Incident No:**  
**Responsible Party:** Oneok Rockies Midstream, LLC.  
**Date Incident:** 3/1/2016      **Time Incident:** 1400      **Duration:** 1 hours  
**County:** Dunn      **Twp:** 146      **Rng:** 95      **Sec:** 28      **Qtr:** NE  
**Lat:** 47.44334      **Long:** -102.79160      **Method:** Interpolation from map  
**Location Description:** 5 Miles north of Killdeer, ND

**Submitted By:** George Soto      **Affiliation:** Optimized Process Design  
**Address:** 25610 Clay Rd.  
**City:** Katy      **State:** TX      **Zip:** 77493

## Received By:

**Contact Person:** Nadia Kyrlova  
2700 Lincoln Avenue SE  
Sidney, ND 59270

**Distance Nearest Occupied Building:** 0.84 Miles      **Release Contained:** Yes

**Type of Incident:** Fill hose came out of fill spout on tank during filling operations.

**Description of Released Contaminant:** Hydraulic Fuel

**Volume Spilled:** 0.90 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** Unknown      **Reported to NRC:** Unknown

## Cause of Incident:

Mobile Crane onsite had a small hydraulic leak from a hose.

## Risk Evaluation:

none

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

none

## Action Taken or Planned:

Once leak was discovered the crane was put out of service until the leak was fixed. Contaminated soil was dug up, bagged and placed into a contaminated soil containment until Western Choice Cooperative picked up containment for disposal. Crane was fixed by equipment vendor.

**Wastes Disposal Location:** Western Choice Cooperative will pick up metal containment with excavated and bagged soil. OPD will get Bill of Lading for disposal verification.

## Agencies Involved:

## **Updates**

---

**Date:** 3/9/2016      **Status:** Reviewed - Follow-up Required

**Author:** O'Gorman, Brian

**Updated Volume:**

**Notes:**

According to the report, .9 gallons of hydraulic fluid leaked onto site soil. Further follow-up needed.

---

**Date:** 3/17/2016      **Status:** Inspection

**Author:** Washek, Sandi

**Updated Volume:**                      0.90 gallons

**Notes:**

Arrived on site at 11:30 a.m. Weather was overcast with snow, wind out of the NW at 20 mph, temperature was 21 degrees F. Met with company rep on site and was informed that an NDDoH inspector had looked at the site last week. I inspected the site and reviewed the waste disposal report. The waste was sent to Renewable Resources. Additional information will be added.

---

**Date:** 4/28/2016      **Status:** Correspondence

**Author:** Cooper, Mike

**Updated Volume:**

**Notes:**

Talked with site safety supervisor who said that the material was disposed of in a roll-off bin and will be tested and disposed of by Western Choice Cooperative. Site has been scraped clean. Constant construction around area of spill. Moving to close this site and spill.